

**From:** [Jonathan Carroll](#)  
**To:** [Moore, Gary](#)  
**Cc:** [Steven Wilson](#)  
**Subject:** Re: Tank 16 Patch bottom  
**Date:** Thursday, September 26, 2013 6:15:23 PM  
**Attachments:** [J41644-1 Std. Tal. L2 Rev\(1\) Final Report.pdf](#)

---

FYI

YES,  
BBB took samples. Sorry for the delay, We did not hire TestAmerica, they were hired by BBB.  
They were not immediately responsive to us, we had to go through BBB to get the attached report.

BBB will be putting in a double bottom, using the slotted shell method, as demonstrated in their proposal, unless you have some objection(s).

Regards,

Jonathan Carroll

---

**From:** "Moore, Gary" <Moore.Gary@epa.gov>  
**To:** Jonathan Carroll <JCarroll@lazarusenergy.com>  
**Sent:** Tuesday, September 24, 2013 12:19 PM  
**Subject:** RE: Tank 16 Patch bottom

**Jonathan:**

**I looked it up and my understanding is that the slotted shell method is used to put in a double bottom. I assume that you are repairing the current bottom of Tank 16 and then putting in a double bottom. I am not exactly sure what you guys are doing.**

**I also understand that you guys took samples of the sand beneath Tank 16. Do you have any results back as of yet?**

**Thanks**

**Gary Moore**

**Federal On-Scene Coordinator**

**U.S. EPA Region 6**

**214-789-1627 cell**

**214-665-6609 office**

**[moore.gary@epa.gov](mailto:moore.gary@epa.gov)**

---

**From:** Jonathan Carroll <JCarroll@lazarusenergy.com>  
**Sent:** Tuesday, September 24, 2013 11:54 AM  
**To:** Moore, Gary  
**Subject:** Re: Tank 16 Patch bottom



9568274

No, and No.

---

**From:** "Moore, Gary" <Moore.Gary@epa.gov>  
**To:** Jonathan Carroll <JCarroll@lazarusenergy.com>  
**Sent:** Tuesday, September 24, 2013 11:53 AM  
**Subject:** RE: Tank 16 Patch bottom

**Jonathan:**

**Have you decided to replace the entire tank bottom? Did the report show that this was necessary?**

**Thanks**

**Gary Moore**

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

[moore.gary@epa.gov](mailto:moore.gary@epa.gov)

---

**From:** Jonathan Carroll <JCarroll@lazarusenergy.com>  
**Sent:** Tuesday, September 24, 2013 11:37 AM  
**To:** Moore, Gary  
**Cc:** Steven Wilson  
**Subject:** Fw: Tank 16 Patch bottom

What do you want us to do? see attached.

----- Forwarded Message -----

**From:** Andrew Martin <ajm@bbbtanksvc.com>  
**To:** jcarroll@lazarusenergy.com  
**Cc:** bobswain@bbbtanksvc.com; 'Jacob Swain' <jacobswain@bbbtanksvc.com>; garythompson@bbbtanksvc.com  
**Sent:** Tuesday, September 24, 2013 7:50 AM  
**Subject:** Tank 16 Patch bottom

Jonathan – Please see attached changes as well as comparisons per your request. I will call and follow up this morning with you accordingly. Thanks a for your time and consideration.

Andrew "Andy" J. Martin  
Director  
BBB Tank Services, Inc.  
162 Independence Pkwy N  
Baytown, Texas 77520  
Office: 832.695-2132  
Fax: 281.838-8748

Cell: 832.724.3149

[ajm@bbbtanksvc.com](mailto:ajm@bbbtanksvc.com)

[www.bbbtankservices.com](http://www.bbbtankservices.com)